## FORMAT OF CERTIFICATE TO BE ISSUED BY THE DISTRICT EDUCATION OFFICER IN RESPECT OF SCHOOLS SEEKING AFFILIATION WITH THE CENTRAL BOARD OF SECONDARY EDUCATION

(In accordance with School Safety Policy, 2016 issued by the NDMA, Manual on Safety and Security of Children in Schools developed by NCPCR and the National Building Code)

## PART-A

(This part is to be filled-up by the school and to be produced before the District Education Officer along with all supporting documents and certificates in original)

GE	NERAL INFORMATION	
1	Name of the School:  (Name should be exactly as per NOC and recognition certificate)	Maharani Geeta Devi Educational centre
2	Address of the School:	Malipur, Ambedkar Nagar 224159
3	U-DISE code allotted to the school:	09480603317
4	Name and address of the Trust/Society/ Company(under section-8) running the School	Rama Nand Geeta Devi Seva Sansthan Malipur, Ambedkar Nagar, 224159
5	Is the Trust/Society/ Company duly registered with the competent registering authority and the registration is valid as on date?	Yes, 10/01/2021
6	Proposed affiliation with CBSE for:	Senior Secondary
7	Location of school	Outside the Municipal limits of any town/city.

(Signature of Principal)

जिला (डीहुमालाय निरीक्षक अम्बेडकरनगर २०११/२०२१

Sadanavd shuklo

8 Is the School already affiliated to any board for Class X or XII examinations?  9 Standard/level/class up to which the school is running:  10 Has the school obtained No Objection Certificate from the State Government for Affiliation with CISS?  11 Number of NOC and date of issue:  12 Has the school obtained Recognition Certificate from the State Government from class-1 to 8th and date of issue:  13 Number of Recognition Certificate from class-1 to 8th and date of issue:  14 Manyata / 9248-53 / 2013-14 03-01-2014  15 Number of Recognition Certificate from class-1 to 8th and date of issue:  16 Manyata / 9248-53 / 2013-14 03-01-2014  18 Is the school situated on a single contiguous plot of land bounded on all sides by a Pucca Boundary Wall?  15 Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  16 Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  17 The land is in the possession of the school/ Trust/society/Company legally by way of:  18 Name of the Owner/Lessee of the land in respect of point-15 above:  19 In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  20 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  10 In Case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  21 Lase the school been inspected by the Government engineer and the school  22 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  23 Has the school been inspected by the Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  24 Has the school compound been checked by the public health department and the health and santary conditions been found to be satisfactory and the water has been					
INFORMATION REGARDING NOC AND RECOGNITION CERTIFICATE  10 Has the school obtained No Objection Certificate from the State Government for Affiliation with CBSE?  11 Number of NOC and date of issue:  12 Has the school obtained Recognition Certificate from the State Government from class-1 to 8 <sup>th</sup> ?  13 Number of Recognition Certificate from class-1 to 8 <sup>th</sup> and date of issue:  14 Is the school obtained Recognition Certificate from class-1 to 8 <sup>th</sup> and date of issue:  15 Manyata /9248-53 /2013-14 03-01-2014  16 InfoRMATION REGARDING LAND DETAILS AND OWNERSHIP  16 Is the school situated on a single contiguous plot of land bounded on all sides by a Pucca Boundary Wall?  17 Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  18 Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  19 Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  10 The land is in the possession of the school/ Trust/Society/Company legally by way of:  11 Lease deed  12 Maharani Geets Devi Educational Centre Malipur Ambedikar Nagar  19 In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  20 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  1NFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  21 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22 Has the school compound been checked by the public health department and the health and school building been found to be satisfactory and the water has been found safe for drinking?  23 His the school compound been checke	8	Is the School already affiliated to any board for Class-X or XII examinations?	NO		
Has the school obtained No Objection Certificate from the State Government for Affiliation with CBSE?  11 Number of NOC and date of issue:  12 Has the school obtained Recognition Certificate from the State Government from class-1 to 8 <sup>th</sup> ?  13 Number of Recognition Certificate from class-1 to 8 <sup>th</sup> and date of issue:  14 Is the school statuted on a single contiguous plot of land bounded on all sides by a Pucca Boundary Wall?  15 Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  16 Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  17 The land is in the possession of the school/Trust/Society/Company legally by way of:  18 Name of the Owner/Lessee of the land in respect of point-15 above:  19 In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  20 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  21 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21(a) If yes the date of last inspection:  22(b) If yes the date of last inspection:  23 Sharp school been inspected by the officer of Government Fire Department and the school building been found structurally safe for running a school?  23 Has the school been inspected by the public health department and the health and	9	Standard/level/class up to which the school is running:	I - VIII		
Sovernment for Affiliation with CBSE?	INFORMATION REGARDING NOC AND RECOGNITION CERTIFICATE				
Has the school obtained Recognition Certificate from the State Government from class-1 to 8"?  Number of Recognition Certificate from class-1 to 8" and date of issue:  Manyata / 9248-53 /2013-14 03-01-2014  INFORMATION REGARDING LAND DETAILS AND OWNERSHIP  Is the school situated on a single contiguous plot of land bounded on all sides by a Pucca Boundary Wall?  Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  17 The land is in the possession of the school/ Trust/Society/Company legally by way of:  Lease deed  Name of the Owner/Lessee of the land in respect of point-15 above:  Mahazani Geeta Devi Educational Centre Malipur Ambedkar Nagar  19 In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  20 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  21 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21 Has the school been inspected by the Officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  3 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23 Has the date of last inspection:  3 O7/04/2017	10		No , Under Process		
Sovernment from class-1 to 8 <sup>th</sup> ?   Number of Recognition Certificate from class-1 to 8 <sup>th</sup> and date of issue:   Manyata / 9248-53 /2013-14   03-01-2014     INFORMATION REGARDING LAND DETAILS AND OWNERSHIP   14	11	Number of NOC and date of issue:			
INFORMATION REGARDING LAND DETAILS AND OWNERSHIP  14 Is the school situated on a single contiguous plot of land bounded on all sides by a Purca Boundary Wall?  15 Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  16 Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  17 The land is in the possession of the school/ Trust/Society/Company legally by way of:  18 Name of the Owner/Lessee of the land in respect of point-15 above:  19 In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  20 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  21 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21(a) If yes the date of last inspection:  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  24 O7/04/2017	12		YES		
Is the school situated on a single contiguous plot of land bounded on all sides by a Pucca Boundary Wall?  Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  6125 square meters  The land is in the possession of the school/ Trust/Society/Company legally by way of:  Lease deed  Name of the Owner/Lessee of the land in respect of point-15 above:  Maharani Geeta Devi Educational Centre Malipur Ambedkar Nagar  In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  FROM 22-03-2017 TO 21-03-2047 TOTAL 30 YEARS  Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  I Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  PES  14 Has the school been inspected by the officer of Government Fire Department and the school building been found structurally safe for school from the point of view of fire safety?  25 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  26 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  27 Has the date of last inspection:  28 O7/04/2017	13	Number of Recognition Certificate from class-1 to 8 <sup>th</sup> and date of issue:			
a Pucca Boundary Wall?  Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?  Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  The land is in the possession of the school/ Trust/Society/Company legally by way of:  Lease deed  Name of the Owner/Lessee of the land in respect of point-15 above:  Maharani Geeta Devi Educational Centre Malipur Ambedkar Nagar  In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  FROM 22-03-2017 TO 21-03-2047 TOTAL 30 YEARS  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  YES  Type of the safety of	INFOR	MATION REGARDING LAND DETAILS AND OWNERSHIP	•		
by a single continuous Boundary Wall on all sides?  Total area (in square meters) in respect of 14 and 15 above on which the school is situated:  6125 square meters  The land is in the possession of the school/ Trust/Society/Company legally by way of:  Lease deed  Name of the Owner/Lessee of the land in respect of point-15 above:  Maharani Geeta Devi Educational Centre Malipur Ambedkar Nagar  In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  That the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  The sthe school been inspected by the Officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  The sthe school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  The sthe school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  The land is in the possession of the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?	14		YES		
The land is in the possession of the school/ Trust/Society/Company legally by way of:  Lease deed  Name of the Owner/Lessee of the land in respect of point-15 above:  Maharani Geeta Devi Educational Centre Malipur Ambedkar Nagar  In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  In sany public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  NO  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  21 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21(a) If yes the date of last inspection:  22 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23 If yes the date of last inspection:  24 O7/04/2017	15	Are both the School and the Play Ground situated in a single compound bounded by a single continuous Boundary Wall on all sides?	YES		
Name of the Owner/Lessee of the land in respect of point-15 above:  Maharani Geeta Devi Educational Centre Malipur Ambedkar Nagar  In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  State Government norms, the period of the lease:  Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  If yes the date of last inspection:  25/01/2018  Has the school been Inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  If yes the date of last inspection:  20/10/2017  Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  If yes the date of last inspection:  07/04/2017	16	Total area (in square meters) in respect of 14 and 15 above on which the school is situated:	6125 square meters		
In case the land is in the possession of the society/school by way of lease as per State Government norms, the period of the lease:  Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  If yes the date of last inspection:  21 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for d7/04/2017	17	The land is in the possession of the school/ Trust/Society/Company legally by way of:	Lease deed		
State Government norms, the period of the lease:  10 Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?  10 INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  11 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  11 If yes the date of last inspection:  12 If yes the date of last inspection:  13 If yes the date of last inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  12 If yes the date of last inspection:  13 If yes the date of last inspection:  14 If yes the date of last inspection:  15 If yes the date of last inspection:  16 If yes the date of last inspection:  17 If yes the date of last inspection:  18 If yes the date of last inspection:  19 If yes the date of last inspection:  10 If yes the date of last inspection:  10 If yes the date of last inspection:  10 If yes the date of last inspection:	18	Name of the Owner/Lessee of the land in respect of point-15 above:			
INFORMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS  21 Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21(a) If yes the date of last inspection:  25/01/2018  22 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  07/04/2017	19		Consequence About 1 August 1 August 1		
Has the school been inspected by the Government engineer and the school building been found structurally safe for running a school?  21(a) If yes the date of last inspection:  25/01/2018  Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  07/04/2017	20	Is any public road, canal or thorough-fare, HT line etc. passing through the land in respect of point-16 above?	NO		
building been found structurally safe for running a school?  21(a) If yes the date of last inspection:  25/01/2018  21 Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  25/01/2018  YES	INFO	RMATION REGARDING ESSENTIAL SAFETY REQUIREMENTS			
Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  07/04/2017	21		YES		
school building been declared safe for school from the point of view of fire safety?  22(a) If yes the date of last inspection:  23 Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  07/04/2017	21(a)	If yes the date of last inspection:	25/01/2018		
Has the school compound been checked by the public health department and the health and sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  07/04/2017	22	Has the school been inspected by the officer of Government Fire Department and the school building been declared safe for school from the point of view of fire safety?	YES		
sanitary conditions been found to be satisfactory and the water has been found safe for drinking?  23(a) If yes the date of last inspection:  07/04/2017	22(a)	If yes the date of last inspection:	20/10/2017		
	23	sanitary conditions been found to be satisfactory and the water has been found safe for	YES		
	23(a)	If yes the date of last inspection:	07/04/2017		

Signature of Principal

जिला ह विद्यालय ा तिरीक्षक अम्बेडकरनगर २८११ २०२१

Salamand Shuk()

INF	DRMATION REGARDING THE STAFF					
24.	Does the school have well defined					
	Does the school have well defined service rules and conditions for its employees as per prevalent norms of appropriate Government?	Yes				
25.	Is the school paying salary to the	763				
	Is the school paying salary to the teachers and other employees as per the norms or the appropriate Government?	Yes				
26.	Is the salary to the teach	163				
	Is the salary to the teachers and other employees of the school being paid through the bank by mode of electronic clearing?	Yes				
	(Payment by cheque or each a starting?	res				
	(Payment by cheque or cash to the individuals is not allowed)					
	Masarani Barrani Bruklo	,				
	Shuklo	Anja.				
	Madarani Gama 7 (Carpi Gantra	History				
	Signature of school Manager Stone	O Contra				
	Signature of 20	hool Principal II. 155				
(This	part is to be filled-up by the District Education Officer after verifying all supporting doc nal and visiting the school)					
origi	nal and visiting the school	liments and accuse				
	g und seriour)	differents and certificates in				
File I	No					
	Date of issuance	291				
1.	This is to comit at a second s	0-2-1				
	documents 8 as a sign and the information above, provided by the school has been used.					
	This is to certify that the information above, provided by the school has been verified documents & certificates and visiting the school and the information has been found of the school recommended for efficiency.	on the basis of all supporting				
2.	Is the school recommended for estillar and a school recommended for es					
	rease ensure that the school fulfile land and a					
	(Please ensure that the school fulfils land requirements also as per details given in					
3.	Recommended for Middle Class Syllabus (Second - 10					
	Recommended for Middle Class Syllabus/Secondary/Senior Secondary to CBSE?					
	. Mr					
	जिला विद्यालय निरीक्षक					
		Signature				
(DISTRICT EDUCATION OFFICER) / FOLIVALENT OFFICER						
	NAME OF DISTRICT:					

## PART-C

## STRICT EDUCATION OFFICER SHALL PUT A <u>TICK MARK AGAINST THE COLLUMN UNDER</u> WHICH THE SCHOOL IS FULFILLING THE LAND CRITERIA

Name and Address of the school:  Maharani Geeta Devi Educational Centre  Malipur, Ambedkar Nagar, 224159		Total Land area in lawful possession of school is 6125 Square Meters	
SN	LOCATION OF SCHOOL	LAND REQUIREMENT	PLEASE TICK THE CONCERNED COLUMN
1.	Any Where in India	Minimum 6000 Square Meters	V
2.	In Municipal limits of cities with a population exceeding 15 Lakhs.	Minimum 4000 Square Meters	×
3.	In hilly areas prescribed by the Planning Commission (NITI Aayog)	Minimum 4000 Square Meters	×
4.	In Municipal Limits of the State Capital Cities.	Minimum 4000 Square Meters	×
5.	In the North Eastern States.	Minimum 4000 Square Meters	×
6.	In the state of Jammu and Kashmir	Minimum 4000 Square Meters	×
7.	In Municipal limits of Ghaziabad. NOIDA, Faridabad and Gurugram Cities	Minimum 4000 Square Meters	×
8.	In the Municipal Limits of Panchkula and Mohali/SAS Nagar	Minimum 4000 Square Meters	×
9.	In the Municipal Limits Class-X cities (Ahmedabad, Bengaluru, Hyderabad, Pune) Or on the Hill Stations. (For Senior Secondary Level)	Minimum 2000 Square Meters	×
10.	In the Municipal Limits Class-X cities (Ahmedabad, Bengaluru, Hyderabad, Pune) Or on the Hill Stations. (For Senior Secondary Level)	Minimum 3000 Square Meters	×
11.	In the Municipal Limits of Chennal, Delhi, Kolkata and Mumbai Or the state of Arunachal Pradesh.  Or the state of Sikim Or the Islands.  (For Secondary Level)	Minimum 1600 Square Meters	×
12.	In the Municipal Limits of Chennai, Delhi, Kolkata and Mumbai Or the state of Arunachal Pradesh.  Or the state of Sikim Or the Islands.	Minimum 2400 Square Meters	×

जिला विद्यालय निरीक्षक

NAME AND STAMP OF ISSUING D.E.O.(DISTRICT EDUCATION OFFICER) / EQUIVALENT OFFCER FROM EDUCATION ADMINISTRATION AT DISTRICT (EV) / 1 / 2821

NAME OF DISTRICT: Ambedkar Nagar, UP

(For Secondary Level)